



the **play inspection** company

Annual Inspection

Bugbrooke Parish Council

School Lane Play Area

Next to Primary School, Northampton, NN7 3PA



API Associate



Unit 5, Glenmore Business Park, Blackhill Road, Poole, Dorset, BH16 6NL
t- 01202 590675 e- info@playinspections.co.uk

[www. playinspections .co.uk](http://www.playinspections.co.uk)



Inspection Scope for RPII Annual Inspectors

This document outlines the RPII scope for inspections undertaken by the Inspectors listed as Indoor and Outdoor Annual Inspectors (where relevant) on the RPII Register of Inspectors when undertaking inspections.

Inspections are undertaken with reference to the standards listed in this preamble only; where no date for the standard is given it will be the standard that is current at the time of inspection except where overlap periods are granted by the standards committee when standards are updated. The information contained in reports is provided to assist the owner/operator in fulfilling their responsibilities as detailed in the relevant standard. Other standards referenced within the listed standards do not form part of the inspection, unless they are also explicitly listed here.

For the avoidance of doubt, references to compliance relate only to those aspects that can be assessed visually or manually, within the limitations of a non-dismantling, non-destructive inspection, and without the use of specialist equipment.

The following standards define the technical framework within which inspections are carried out; not all requirements within these standards can be verified during an inspection. The following standards are relevant to all installations of equipment that are publicly accessible to users; this includes public parks, pay and play parks, schools, nurseries, public houses, holiday parks, indoor play centres, farm parks etc. All equipment used or employed in publicly accessible areas should meet with the requirements of the relevant standards (listed below):

BS EN 1176 Parts 1, 2, 3, 4, 5, 6, 10 & 11 Playground equipment intended for permanent installation outdoors & indoors.

BS EN 1176 Part 7 - 'Guidance on Installation, Inspection, Maintenance and Operation' (this document gives guidance to the owners/operators of the facility on the installation, inspection, maintenance and operation of playground equipment, excluding ancillary items).

In the United Kingdom the National Foreword forms an important part to the understanding and implementation of the recommendations set out in this document. It clarifies the application of the document within the UK as best practice guidance, as the document has been used since its initial publication. Therefore, in the UK this standard (BS EN 1176 – Part 7) contains no requirements and needs to be read and implemented as guidance, with the use of the term 'shall' therefore becoming a recommendation, as in the term 'should'.

Domestic play equipment falls outside of the scope of BS EN 1176 and has its own standards (BS EN 71 series – Safety of Toys). Where domestic equipment can be identified this will be acknowledged in the report; any comments will be made using the principles of BS EN 1176 as guidance only, rather than as a formal assessment of compliance.

When water play items, including spray parks, are inspected any comments concerning compliance within the inspection will refer to EN 1176. We have not assessed these against the requirements of EN 17232 (Water play equipment and features).

Other equipment that is not clearly identified as unsupervised or domestic (natural play, self-build equipment etc.) will be assessed for compliance with the relevant standard listed below:

- BS EN 15312** Free access multi-sports equipment
- BS EN 14974** Skateparks
- BS EN 16630** Permanently installed outdoor fitness equipment
- BS EN 16899** Parkour equipment (plus RPII/API guidance notes)

Annual and Post Installation inspections will take into consideration compliance with these current standards, and defects related to wear and vandalism. Items not listed in the report have not been included in the inspection. The inspection will cover the playground equipment and the active area (that area which is obviously part of the playground), nominally up to three metres around, the fence line if closer, or other areas as agreed.

Operational inspections only take into consideration defects related to cleanliness, equipment ground clearances, ground surface finishes, exposed foundations, sharp edges, missing parts, excessive wear (of moving parts) structural integrity, wear and vandalism. Routine visual inspections relate only to the most obvious defects such as broken or missing parts, litter, vandalism and issues created by severe weather conditions (the intention is to identify hazards created by storm damage).

All inspections are non-dismantling, non-destructive and do not include any structural, toxicology or impact assessments defined in the standard; however, the inspector will undertake a basic manual stability check appropriate to a visual

inspection and if equipment fails under manual load, or any other hazard is identified as an unacceptable risk, the owner/operator will be notified as soon as practicably possible.

The inspector will access all reasonably accessible equipment and will assess all reasonably accessible parts above the standing surface. For the purposes of this inspection, “reasonably accessible” means accessible without the use of specialist access equipment, tools, or unsafe working practices. Where it is not possible to access parts of the equipment without employing an alternative means of access the report will record the action required by the owner/operator to ensure the continued safe use of the equipment.

Ancillary equipment will be assessed using the inspector’s knowledge and experience of the standards named in this document. (Note: Ancillary items are not included in the specific equipment-type parts of the EN 1176 series; hence they are not assessed for compliance with EN 1176 series and are subject to a general safety assessment).

The owner/operator is responsible for the overall safety of the equipment and area.

The inspector will not undertake any of the following works unless specifically agreed in writing at the time of order:

Checking the depth and underlying structural integrity of any surface areas and/or carrying out any testing of the impact attenuating properties of any surfaces; the identification of any corrosion, rot or other deterioration in any apparatus or equipment other than by an external inspection; the inspection of any equipment (or part thereof) that is beneath the playing surface (loose-fill materials may be moved to expose foundations); tightening any bolts, hinges or other fixing devices on any apparatus or equipment; assessing or inspecting any electrical installations contained on any site and/or apparatus and/or equipment; assessing or inspecting any water supplies and/or water features and/or any associated computerised systems (including carrying out any programming); where planting or trees are mentioned in the report no assessments of toxicity, suitability or condition are undertaken – the owner/operator should have suitable inspections provided by a competent person.

The owner/operator should have a ‘design risk assessment’ provided by the manufacturer/designer of the area for the equipment and location in which the facility is installed.

The operator is responsible for managing risks of their provision and is required by law to carry out a ‘suitable and sufficient assessment’ of the risks associated with a site or activity. This inspection shall be considered as contributing to the operator's discharge of this responsibility.

The details contained within the report are a snapshot of the condition at the time of inspection only and subsequent events may affect the condition of the facility. Suggested remedial actions are based on the knowledge and experience of the inspector and/or that of the inspection company. The owner/operator should always seek the advice of the manufacturer or a competent person when undertaking repairs and/or modifications to equipment.

Responsibility of the Owner/Operator The owner/operator has overall responsibility for the safety, management, and ongoing maintenance of the play equipment and surrounding area. This includes ensuring that equipment is appropriately installed, inspected, maintained, repaired, and managed in accordance with the relevant standards, manufacturer guidance, and applicable legislation

Inspections undertaken by RPII Annual Inspectors contribute to the owner/operator’s discharge of these responsibilities but do not replace the requirement for the owner/operator to carry out suitable and sufficient risk assessments, routine monitoring, and maintenance, or to act on identified defects and recommendations. Responsibility for initiating or undertaking any actions arising from this report rests solely with the Client.

The operator is responsible for following the guidance of the relevant standards. The standards give guidance on the installation, inspection, maintenance and operation of the various types of facilities. The inspection guidance is listed in Table 1, with an indication of which parts will be included in an RPII Annual or Post-Installation Inspection. The relevant standards also contain additional parts which the operator should follow.

Inspection recommendations of relevant standards Inclusion or exclusion within this table does not imply an exhaustive assessment; all inspections and checks are subject to the limitations described within this methodology. Refer to relevant standards for full text	Annual Main	RPII Annual/ Post Installation Inspection
6.1 d) Overall levels of safety of equipment (see note 1)	✓	✓ [1]
6.1 d) Overall levels of safety of foundations (see note 1)	✓	✓ [1]
6.1 d) Overall levels of safety of playing surfaces (see note 2)	✓	✓ [2]
6.1 d) Compliance with the relevant parts of the standard and or risk assessment (see note 3)	✓	✓ [3]
6.1 d) Effects of weather	✓	✓
6.1 d) Presence of rot, decay or corrosion (see note 1)	✓	✓ [1]
6.1 d) Assessment of repairs made or added or replaced components (see note 4)	✓	✓ [4]
6.1 d) Excavation or dismantling/additional measures	✓	✗
6.2.1 Assessment of glass reinforced plastics (see note 5)	✓	✓ [5]
6.2.1 Inspection of one post equipment (see note 1)	✓	✓ [1]
6.2.4 Undertaking the Operators inspection protocol	✓	✗

NB: The clause numbers in table 1 are taken from BS EN 1176 - Part 7:2020. The content is equally applicable to all other relevant standards listed herein. Playgrounds contain a range of equipment from different manufacturers and installed over a number of years; operators should implement any guidance provided by the manufacturer. Item specific detail is not readily available to RPII Playground Inspectors, whose report contributes to the operator's overall inspection responsibilities as detailed in the relevant standards. RPII Annual Inspectors may, where readily available, refer to manufacturer installation instructions for general context, but do not check against these in full on any item as inspections are focused on compliance with relevant standards and maintenance defects; the responsibility for ensuring that installation instructions are adhered to lies with the owner and the installer.

[1] A manual test only is undertaken for stability. Wear and instability are only detectable where readily apparent without dismantling or destruction and without the use of tools, excavation or specialist equipment. Rot and corrosion are tested or with a hammer and/or steel rod. Decay in timber may exist which can only be found with specialist equipment.

[2] Only the visible condition and dimensional compliance of surface extent is considered. Neither testing of impact attenuating properties nor measurement of the thickness of bound surfaces are undertaken on RPII annual inspections.

[3] The inspection assesses compliance where this can be tested on site using manual methods without dismantling, destruction and without the use of tools or specialist equipment.

[4] The operator should use manufacturer's recommended parts, or equivalent. We are unable to verify if such parts have been used, and any subsequent change in quality or performance.

[5] Visible glass fibres will be noted in reports. The operator is responsible for repairs or replacement.

Risk Assessment Matrix

			Scores in the report are multiplication factors of Likelihood x Severity					
			Severity>>					
Likelihood	Very High probability, if the situation is not addressed an accident is almost certain.	5	Very High	VL (5)	L (10)	M (15)	H (20)	VH (25)
	High probability an accident is probable without any added factor.	4	High	VL (4)	L (8)	M (12)	H (16)	H (20)
	Moderate probability an incident is foreseeable.	3	Moderate	VL (3)	L (6)	L (9)	M (12)	M (15)
	Some probability, requires a combination of factors to take place.	2	Low	VL (2)	VL (4)	L (6)	L (8)	L (10)
	No significant probability; lightning strike, freak accident.	1	Very Low	VL (1)	VL (2)	VL (3)	VL (4)	VL (5)
				Very Low	Low	Moderate	High	Very High
				1	2	3	4	5
				No injury likely e.g. damaged or soiled clothing, minor bruising, grazes	Minor injury, laceration or bruising requiring first aid only	Injury requiring medical intervention e.g. cuts requiring stitches	Serious injury including concussions or fracture of long bones	Severe injury involving a potential life changing injury or fatality
				Severity>>				
Note 1: The total risk scores included within our reports are a multiplication factor of the calculated Likelihood and Severity of each finding. Both Likelihood and Severity are given a number between 1 - 5 as shown on the matrix above and these two numbers are then multiplied together to give the total risk score that is shown against defects on the report. Total risk scores can be divided in both directions, i.e. a total risk score of 12 could be a Likelihood (3) x Severity (4) or Likelihood (4) x Severity (3). Note 2: When we inspect we only see a snapshot of the current condition of the equipment. It is the operators responsibility to ensure that there is a continuing level of maintenance to keep the equipment in good working order and the site fit for use.								

School Lane Play Area

Inspection Ref: 3132662

Site Ref: 79677

Inspected: 30-June-2026 - 12:13 by Jamie Leeson (RPII Annual Inspector)

Risk Assessment: 10 Low Risk



Location:

The site is located in an area of public open space and is not directly overlooked by any properties in the local community.

Disabled Access:

Some accessible features - The area includes limited accessible elements; however, aspects of the layout, surfacing, or equipment may present barriers to use for some people with disabilities without reasonable adjustments or assistance.

i 6 - Low Risk

Item: Site General
Manufacturer: Owner/Operator
Surface Type: N/A
Item Quantity: 1
Equipment Compliance: N/A
Surface Area Compliance: N/A

Total Findings: 2



Finding 1

There is weed / vegetation growth within the surface -
 Remove weed / vegetation growth

Finding 2

There is a risk of head and neck entrapment in the
 accessible castellations of the fence and gate - Monitor - no
 action given the risk assessment

i 4 - Very Low Risk

Item: Sign
Manufacturer: Not Identified
Surface Type: N/A
Item Quantity: 1
Equipment Compliance: N/A
Surface Area Compliance: N/A

Total Findings: 1



Finding 1

This item is satisfactory - no work required -

i 10 - Low Risk

Item: Gate
Manufacturer: Not Identified
Surface Type: Bark Mulch
Item Quantity: 1
Equipment Compliance: N/A
Surface Area Compliance: N/A

Total Findings: 3



Finding 1

There are openings that are less than 12mm that could trap or crush fingers - Provide a 12mm gap throughout full range of motion at both sides of gate

Finding 3

There is surface corrosion / rust present on the item - Consider treating the item

Finding 2

The rubber buffer is missing from the latch plate - Replace rubber buffer

i 6 - Low Risk

Item: Fence
Manufacturer: Not Identified
Surface Type: Grass
Item Quantity: 1
Equipment Compliance: N/A
Surface Area Compliance: N/A

Total Findings: 1



Finding 1

A number of fixings have worked loose around the fencing - Secure all loose fixings

i 8 - Low Risk

Item: Bench
Manufacturer: Not Identified
Surface Type: Grass
Item Quantity: 1
Equipment Compliance: N/A
Surface Area Compliance: N/A

Total Findings: 2



Finding 1

The area around the item has eroded and may become slippery - Reinstate eroded area

Finding 2

There is some graffiti present - Remove the graffiti

i 6 - Low Risk

Item: Chair Spinner
Manufacturer: Proludic
Surface Type: Bonded Rubber Mulch
Item Quantity: 1
Equipment Compliance: Yes
Surface Area Compliance: Yes

Total Findings: 1



Finding 1

This item is satisfactory - no work required -

i 8 - Low Risk

Item: 1 Bay Mixed Seat, 1 Cradle, 1 Flat
Manufacturer: Safe & Sound
Surface Type: Bonded Rubber Mulch
Item Quantity: 1
Equipment Compliance: No
Surface Area Compliance: Yes

Total Findings: 6



Finding 1

BS EN 1176 Part 2: Annex A makes a recommendation that fences or enclosures should be 1.50m from the edges of the swing seat to the sides, and subject to risk assessment, from the edge of the impact area. This is however, a low risk finding and no remedial action is recommended. - Monitor - No action given the risk assessment

Finding 2

The paintwork on this item has been damaged or worn exposing the metal underneath which is rusting / corroding - Treat affected areas and repaint

Finding 3

The swing seat connectors are loose - Tighten to secure

Finding 4

The chain openings are in excess of 8.6mm and do not meet the recommendations of BS EN 1176 Part 1 - Monitor - No action given the risk assessment

Finding 5

There is some notable evidence of chain wear - Monitor for any further deterioration and replace when 40% worn

Finding 6

There is some wear to the shackles - Monitor for any further deterioration and replace when 40% worn

i 8 - Low Risk

Item: Activity Trail
Manufacturer: Not Identified
Surface Type: Bonded Rubber Mulch
Item Quantity: 1
Equipment Compliance: No
Surface Area Compliance: No

Total Findings: 9



Finding 1

The surface has eroded in some areas and may be slippery in wet conditions - Reinstate the surface

Finding 3

There are areas or parts of the timber posts that have rotted - Replace all affected timbers

Finding 5

There is offensive graffiti present - Remove as soon as practicable

Finding 7

The connecting lugs are showing signs of wear - Monitor for any further deterioration and repair as required

Finding 9

There is offensive graffiti present - Remove as soon as practicable

Finding 2

Bolt cap cover/s missing or damaged - Replace

Finding 4

There is some evidence of fire damage to the item - Monitor for any further deterioration and repair as required

Finding 6

The fence forms a hard object within the falling space of the equipment and there is also insufficient surfacing provided in contravention of BS EN 1176 Part 1 - Monitor - No action given the risk assessment

Finding 8

There is some wear to the shackles - Monitor for any further deterioration and replace when 40% worn

i 8 - Low Risk

Item: Multi Play (Junior)
Manufacturer: Lappset UK Ltd
Surface Type: Mixed Surface
Item Quantity: 1
Equipment Compliance: No
Surface Area Compliance: No

Total Findings: 15



Finding 1

The surfacing dimensions are short and do not meet with the requirements of the current applicable standard - Monitor - No action given the risk assessment

Finding 3

There is offensive graffiti present - Remove as soon as practicable

Finding 5

There is algae or moss on the surface of the equipment - Clean and treat appropriately

Finding 7

The unit is easily accessible and has an opening in the barrier to steep play elements in excess of 500mm in contravention of BS EN 1176 Part 1 - Monitor - No action given the risk assessment

Finding 9

There is/are finger entrapment/s in the access element and the item fails to meet the requirements of BS EN 1176 Part 1 4.2.7.6 Entrapment of fingers - Monitor - No action given the risk assessment

Finding 11

The ropes/nets are worn/damaged in places - Monitor for any further deterioration and repair or replace as required

Finding 13

The timber stain is in poor condition - Prepare all affected parts and re-stain with an appropriate preservative

Finding 2

There are a number of dents in the slide surface - Monitor for any further deterioration and repair as required

Finding 4

The item fails to meet the requirements of BS EN 1176 Part 1 4.2.7.2 head and neck entrapment in the barriers and/or steps - Monitor - No action given the risk assessment

Finding 6

There is some evidence of rot in the timber - Monitor for any further deterioration and replace as required

Finding 8

Parts of the timber are rough or splintered - Remove all rough or sharp edges

Finding 10

Bolt cap cover/s missing or damaged - Replace

Finding 12

There is / are post or end caps missing / damaged on the item - Replace missing / damaged post or end caps

Finding 14

The tree canopy overhangs the equipment and is less than 2.0m away - Lift tree canopy to ensure a minimum clearance of 2.0m from the equipment

Finding 15

The grass mats are silted up and the soil is compacted; this may have an effect on the impact absorbing properties of the surface. Consideration should be given to HIC testing the surface to verify impact attenuating properties (<https://playinspections.co.uk/inspection-services/safety-surface-testing/>) - Contact our office for a quotation for this service

Findings information

 6 - Low Risk (Finding 1)			
Item: Ancillary Items - Site General		Risk Level: L - Low Risk	
Manufacturer: Owner/Operator		Surface: N/A	
			
			
Finding: There is weed / vegetation growth within the surface		Action: Remove weed / vegetation growth	

i 5 - Very Low Risk (Finding 2)

Item: Ancillary Items - Site General
Manufacturer: Owner/Operator

Risk Level: V - Very Low Risk
Surface: N/A



Finding: There is a risk of head and neck entrapment in the accessible castellations of the fence and gate
Action: Monitor - no action given the risk assessment

i 10 - Low Risk (Finding 1)

Item: Gates - Gate
Manufacturer: Not Identified

Risk Level: L - Low Risk
Surface: Bark Mulch



Finding: There are openings that are less than 12mm that could trap or crush fingers

Action: Provide a 12mm gap throughout full range of motion at both sides of gate

i 6 - Low Risk (Finding 2)

Item: Gates - Gate
Manufacturer: Not Identified

Risk Level: L - Low Risk
Surface: Bark Mulch



Finding: The rubber buffer is missing from the latch plate

Action: Replace rubber buffer

i 6 - Low Risk (Finding 3)

Item: Gates - Gate
Manufacturer: Not Identified

Risk Level: L - Low Risk
Surface: Bark Mulch



Finding: There is surface corrosion / rust present on the item

Action: Consider treating the item

i 6 - Low Risk (Finding 1)

Item: Fences - Fence
Manufacturer: Not Identified

Risk Level: L - Low Risk
Surface: Grass



Finding: A number of fixings have worked loose around the fencing
Action: Secure all loose fixings

i 8 - Low Risk (Finding 1)

Item: Ancillary Items - Bench
Manufacturer: Not Identified

Risk Level: L - Low Risk
Surface: Grass



Finding: The area around the item has eroded and may become slippery
Action: Reinstate eroded area

i 0 - Risk Assessment not Undertaken (Finding 2)

Item: Ancillary Items - Bench
Manufacturer: Not Identified

Risk Level: N - Risk Assessment not Undertaken
Surface: Grass




Finding: There is some graffiti present

Action: Remove the graffiti

i 8 - Low Risk (Finding 1)

Item: Swings - 1 Bay Mixed Seat, 1 Cradle, 1 Flat
Manufacturer: Safe & Sound

Risk Level: L - Low Risk
Surface: Bonded Rubber Mulch




Finding: BS EN 1176 Part 2: Annex A makes a recommendation that fences or enclosures should be 1.50m from the edges of the swing seat to the sides, and subject to risk assessment, from the edge of the impact area. This is however, a low risk finding and no remedial action is recommended.

Action: Monitor - No action given the risk assessment

i 6 - Low Risk (Finding 2)

Item: Swings - 1 Bay Mixed Seat, 1 Cradle, 1 Flat
Manufacturer: Safe & Sound

Risk Level: L - Low Risk
Surface: Bonded Rubber Mulch




Finding: The paintwork on this item has been damaged or worn exposing the metal underneath which is rusting / corroding

Action: Treat affected areas and repaint

i 6 - Low Risk (Finding 3)

Item: Swings - 1 Bay Mixed Seat, 1 Cradle, 1 Flat
Manufacturer: Safe & Sound

Risk Level: L - Low Risk
Surface: Bonded Rubber Mulch



Finding: The swing seat connectors are loose

Action: Tighten to secure

i 5 - Very Low Risk (Finding 4)

Item: Swings - 1 Bay Mixed Seat, 1 Cradle, 1 Flat
Manufacturer: Safe & Sound

Risk Level: V - Very Low Risk
Surface: Bonded Rubber Mulch




Finding: The chain openings are in excess of 8.6mm and do not meet the recommendations of BS EN 1176 Part 1

Action: Monitor - No action given the risk assessment

i 6 - Low Risk (Finding 5)

Item: Swings - 1 Bay Mixed Seat, 1 Cradle, 1 Flat
Manufacturer: Safe & Sound

Risk Level: L - Low Risk
Surface: Bonded Rubber Mulch





Finding: There is some notable evidence of chain wear

Action: Monitor for any further deterioration and replace when 40% worn

i 6 - Low Risk (Finding 6)

Item: Swings - 1 Bay Mixed Seat, 1 Cradle, 1 Flat
Manufacturer: Safe & Sound

Risk Level: L - Low Risk
Surface: Bonded Rubber Mulch



Finding: There is some wear to the shackles

Action: Monitor for any further deterioration and replace when 40% worn

i 6 - Low Risk (Finding 1)

Item: Activity Equipment - Activity Trail
Manufacturer: Not Identified

Risk Level: L - Low Risk
Surface: Bonded Rubber Mulch



Finding: The surface has eroded in some areas and may be slippery in wet conditions

Action: Reinststate the surface

i 4 - Very Low Risk (Finding 2)

Item: Activity Equipment - Activity Trail
Manufacturer: Not Identified

Risk Level: V - Very Low Risk
Surface: Bonded Rubber Mulch



Finding: Bolt cap cover/s missing or damaged

Action: Replace

 8 - Low Risk (Finding 3)			
Item: Activity Equipment - Activity Trail Manufacturer: Not Identified		Risk Level: L - Low Risk Surface: Bonded Rubber Mulch	
			
			
Finding: There are areas or parts of the timber posts that have rotted		Action: Replace all affected timbers	

i 6 - Low Risk (Finding 4)

Item: Activity Equipment - Activity Trail
Manufacturer: Not Identified

Risk Level: L - Low Risk
Surface: Bonded Rubber Mulch



Finding: There is some evidence of fire damage to the item **Action:** Monitor for any further deterioration and repair as required

i 0 - Risk Assessment not Undertaken (Finding 5)

Item: Activity Equipment - Activity Trail
Manufacturer: Not Identified

Risk Level: N - Risk Assessment not Undertaken
Surface: Bonded Rubber Mulch



Finding: There is offensive graffiti present **Action:** Remove as soon as practicable

i 8 - Low Risk (Finding 6)

Item: Activity Equipment - Activity Trail
Manufacturer: Not Identified

Risk Level: L - Low Risk
Surface: Bonded Rubber Mulch



Finding: The fence forms a hard object within the falling space of the equipment and there is also insufficient surfacing provided in contravention of BS EN 1176 Part 1

Action: Monitor - No action given the risk assessment

 6 - Low Risk (Finding 7)			
Item: Activity Equipment - Activity Trail		Risk Level: L - Low Risk	
Manufacturer: Not Identified		Surface: Bonded Rubber Mulch	
			
Finding: The connecting lugs are showing signs of wear		 Action: Monitor for any further deterioration and repair as required	

i 6 - Low Risk (Finding 8)

Item: Activity Equipment - Activity Trail
Manufacturer: Not Identified

Risk Level: L - Low Risk
Surface: Bonded Rubber Mulch



Finding: There is some wear to the shackles

Action: Monitor for any further deterioration and replace when 40% worn

i 0 - Risk Assessment not Undertaken (Finding 9)

Item: Activity Equipment - Activity Trail
Manufacturer: Not Identified

Risk Level: N - Risk Assessment not Undertaken
Surface: Bonded Rubber Mulch



Finding: There is offensive graffiti present

Action: Remove as soon as practicable

i 5 - Very Low Risk (Finding 1)

Item: Activity Equipment - Multi Play (Junior)
Manufacturer: Lappset UK Ltd

Risk Level: V - Very Low Risk
Surface: Mixed Surface



Finding: The surfacing dimensions are short and do not meet with the requirements of the current applicable standard

Action: Monitor - No action given the risk assessment

i 4 - Very Low Risk (Finding 2)

Item: Activity Equipment - Multi Play (Junior)
Manufacturer: Lappset UK Ltd

Risk Level: V - Very Low Risk
Surface: Mixed Surface



Finding: There are a number of dents in the slide surface

Action: Monitor for any further deterioration and repair as required

i 0 - Risk Assessment not Undertaken (Finding 3)

Item: Activity Equipment - Multi Play (Junior)
Manufacturer: Lappset UK Ltd

Risk Level: N - Risk Assessment not Undertaken
Surface: Mixed Surface



Finding: There is offensive graffiti present

Action: Remove as soon as practicable

i 5 - Very Low Risk (Finding 4)

Item: Activity Equipment - Multi Play (Junior)
Manufacturer: Lappset UK Ltd

Risk Level: V - Very Low Risk
Surface: Mixed Surface



Finding: The item fails to meet the requirements of BS EN 1176 Part 1 4.2.7.2 head and neck entrapment in the barriers and/or steps

Action: Monitor - No action given the risk assessment

i 8 - Low Risk (Finding 5)

Item: Activity Equipment - Multi Play (Junior)
Manufacturer: Lappset UK Ltd

Risk Level: L - Low Risk
Surface: Mixed Surface



Finding: There is algae or moss on the surface of the equipment

Action: Clean and treat appropriately

i 6 - Low Risk (Finding 6)

Item: Activity Equipment - Multi Play (Junior)
Manufacturer: Lappset UK Ltd

Risk Level: L - Low Risk
Surface: Mixed Surface



Finding: There is some evidence of rot in the timber

Action: Monitor for any further deterioration and replace as required

i 8 - Low Risk (Finding 7)

Item: Activity Equipment - Multi Play (Junior)
Manufacturer: Lappset UK Ltd

Risk Level: L - Low Risk
Surface: Mixed Surface




Finding: The unit is easily accessible and has an opening in the barrier to steep play elements in excess of 500mm in contravention of BS EN 1176 Part 1
Action: Monitor - No action given the risk assessment

6 - Low Risk (Finding 8)

Item: Activity Equipment - Multi Play (Junior)
Manufacturer: Lappset UK Ltd

Risk Level: L - Low Risk
Surface: Mixed Surface



Finding: Parts of the timber are rough or splintered

Action: Remove all rough or sharp edges

5 - Very Low Risk (Finding 9)

Item: Activity Equipment - Multi Play (Junior)
Manufacturer: Lappset UK Ltd

Risk Level: V - Very Low Risk
Surface: Mixed Surface



Finding: There is/are finger entrapment/s in the access element and the item fails to meet the requirements of BS EN 1176 Part 1 4.2.7.6 Entrapment of fingers

Action: Monitor - No action given the risk assessment

i 4 - Very Low Risk (Finding 10)

Item: Activity Equipment - Multi Play (Junior)
Manufacturer: Lappset UK Ltd

Risk Level: V - Very Low Risk
Surface: Mixed Surface




Finding: Bolt cap cover/s missing or damaged

Action: Replace

i 6 - Low Risk (Finding 11)

Item: Activity Equipment - Multi Play (Junior)
Manufacturer: Lappset UK Ltd

Risk Level: L - Low Risk
Surface: Mixed Surface



Finding: The ropes/nets are worn/damaged in places

Action: Monitor for any further deterioration and repair or replace as required

i 6 - Low Risk (Finding 12)

Item: Activity Equipment - Multi Play (Junior)
Manufacturer: Lappset UK Ltd

Risk Level: L - Low Risk
Surface: Mixed Surface



Finding: There is / are post or end caps missing / damaged on the item
Action: Replace missing / damaged post or end caps

i 6 - Low Risk (Finding 13)

Item: Activity Equipment - Multi Play (Junior)
Manufacturer: Lappset UK Ltd

Risk Level: L - Low Risk
Surface: Mixed Surface



Finding: The timber stain is in poor condition
Action: Prepare all affected parts and re-stain with an appropriate preservative

6 - Low Risk (Finding 14)

Item: Activity Equipment - Multi Play (Junior)
Manufacturer: Lappset UK Ltd

Risk Level: L - Low Risk
Surface: Mixed Surface



Finding: The tree canopy overhangs the equipment and is less than 2.0m away

Action: Lift tree canopy to ensure a minimum clearance of 2.0m from the equipment

8 - Low Risk (Finding 15)

Item: Activity Equipment - Multi Play (Junior)
Manufacturer: Lappset UK Ltd

Risk Level: L - Low Risk
Surface: Mixed Surface



Finding: The grass mats are silted up and the soil is compacted; this may have an effect on the impact absorbing properties of the surface. Consideration should be given to HIC testing the surface to verify impact attenuating properties (<https://playinspections.co.uk/inspection-services/safety-surface-testing/>)

Action: Contact our office for a quotation for this service